

#### **Meeting Minutes**

# Naval Weapons Station Yorktown (NWSY) Yorktown, Virginia Restoration Advisory Board (RAB) Meeting Wednesday, 18 May 2005, 1830-2030

#### Attendees:

Name	Organization
}	Atlantic Ordnance Command and Representing
CDR Joe Guerrero	NWSY CO CAPT Philip Beierl
LCDR Chris Knudsen	Public Works Officer
Jim Kemp	NWSY Public Affairs Officer
Linda Cole	NAVFAC MIDLANT
Sean Heaney	CNRMA Yorktown Environmental Department
Charles Wilson	CNRMA Environmental
Greyson Franklin	USEPA
Don Joiner	Baker Environmental
Marlene Ivester	Baker Environmental
Wandy Browne	Management Edge
Tim Flood	Management Edge
Jay Dewing	Community Co-Chair
Mrs. Jay Dewing	Community Member
Barry Moss	Community Member
	Community Member and
Elizabeth Rogers	Chesapeake Bay Yorktown Chapter
Cindy Barbeau	Community Member
Holly Kemp	Community Member

[Note: Attachment 1 is the Public Notice for the RAB Meeting. Attachment 2 is the May 2005 RAB Meeting Sign-in Sheet. Attachment 3 is the meeting handout, which contains a hardcopy of the meeting Agenda and Presentations.]

Opening Remarks were presented by Jim Kemp and CDR Guerrero.

CDR Guerrero presented Jay Dewing with a certificate of Acknowledgement of Service and an NWSY coin for his role as the NWSY Community Co-Chair. Mr. Dewing indicated that he has served as Community Co-Chair since the NWSY RAB inception and is stepping down after 10 years of service. His contributions to the NWSY RAB were duly noted.

Linda Cole took the floor for selection of the new Community Co-Chair. Community members Barry Moss and Elizabeth Rogers both volunteered for the position; therefore, an election by the community members was necessary. Each member spoke and expressed their interest in becoming Community Co-Chair. Linda Cole passed out secret ballots for the community members. Wandy Browne collected and counted the votes. Barry Moss was elected as the new Community Co-Chair.



#### **PRESENTATIONS**

#### Work Plan for NWSY Sites 2 and 8 and SSA 14:

Don Joiner took the floor for the first presentation on the Work Plan for NWSY Sites 2 (Turkey Road Landfill) and 8 (Naval Explosives Development Engineering Department (NEDED) Explosives-Contaminated Wastewater Discharge Area) and SSA 14 (Building 537 Discharge to Felgates Creek). Don described the proposed sampling for Site 2. Cindy Barbeau asked, "How do you know that the [proposed sampling area for Site 2] was not originally part of the landfill?" Don replied it was based on visual inspection and where samples were collected for the remedial investigation report. Cindy asked if the debris can be dated to the landfill operations and not later? Don said yes. Don next described the proposed sampling for SSA 14. Elizabeth Rogers asked what was at the bottom of the slope of SSA 14? Don replied a discharge point, marsh grasses, and a channel out to Felgates Creek. Cindy asked, since SSA 14 was steep, could there be contamination further down along Felgates Creek? Don said it could be a possibility. Barry Moss asked if some sampling would occur down the slope of SSA 14. Don replied yes. Elizabeth asked how the proposed sampling tied into any monitoring of Felgates Creek itself? Don replied that Felgates Creek was not part of a monitoring program at this time. Elizabeth asked if VIMS was conducting an oyster study on Felgates Creek? Charlie Wilson replied they do have an oyster reef near the mouth of Felgates Creek, but that VIMS did not come up past the Colonial Parkway. Cindy asked if there were any patterns in the contamination – did it disperse up the creek? Don said there were no known patterns, and the results of the proposed sampling may lead to additional ecological investigation. Cindy asked if Sites 2 and 8 and SSA 14 were under the same task order, regarding funding? Linda Cole replied yes they are; however, Site 2 will be separated out after this initial round of sampling because it is a landfill and will/may involve a larger scope. Elizabeth requested a full-size copy of the presentation to better see the graphics. Linda said she would send it to her. Cindy said it would help to have Site 8 and SSA 14 on the same graphic to see them and the sample results in relation to each other. Don concurred.

#### CAX Site 7 Explosive Safety Submission (ESS)

Linda Cole took the floor for the second presentation on CAX Site 7 (Old DuPont Disposal Area) and clarified that "Site 7" and "Site 7N" were the same. Linda gave a brief background on Site 7's history and the proposed geotube installation. Barry Moss asked if the geotube came in sections? Don Joiner replied yes it did and stated that geotubes were a common type of erosion control, meaning this is a typical application. Cindy Barbeau asked what would happen to the geotube after the eventual cleanup? Linda said it would degrade overtime and the sand inside would replenish the beach. Don further replied that geotubes have a design life and would eventually degrade. Linda described the mortar shell found at Site 7 during the beach cleanup. Barry asked how the Navy was sure there weren't more munitions at the site that possibly would be covered by the geotube? Linda replied that because the ordnance item was found on the beach, it wasn't certain that it originated at Site 7 or was deposited from the tide. In addition, Linda stated that other ordnance items had not been found on CAX previously. However, Linda said because the ordnance item was found and it could not be determined to be inert, an ESS for Site 7 would be necessary and the ESS covers the procedures for looking for ordnance items, meaning there will be an unexploded ordnance (UXO) technician on-site to evaluate anomalies found during the geophysical survey and clear the area before and during geotube installation.



Cindy asked how detailed was the ESS? Linda replied that it was very detailed work plan, covering site history, points of contact, and action plans.

#### NWSY Site 4 ROD: Differences from 2001 PRAP

Don Joiner took the floor for the third and final presentation for the evening. Don described the history of investigations at NWSY Site 4 (Burning Pad Residue Landfill) and explained that the clean-up changed from the proposed industrial level to residential level, which was better than what was originally intended. Cinda Barbeau asked who signed the ROD? Greyson Franklin replied the Navy, the State, and USEPA, Region III. Don also commented that there would be public notification of the availability of the Draft ROD, so the public would have an opportunity to see and comment on the document before it is signed.

#### - End of Presentations -

Barry Moss requested that the last page of the RAB meeting handout be a timeline so the members could better see the big picture for the sites themselves and NWSY as a whole. Linda Cole replied it was a great idea and it would be included. Linda further commented that the Navy would be better at presenting the available budgets for site projects.

Jim Kemp presented the closing remarks and thanked everyone for attending.

Action Items: Linda Cole will send a full-size copy of the presentations to Elizabeth Rogers. Baker will present the results for Site 8 and SSA 14 on the same drawing in order to view the sites and samples results in relation to each other. A timeline for site/project status will be included in future meeting handouts.

Next RAB Meeting: Wednesday, 17 August 2005, 1830 to 2030 Charles E. Brown Park Community Building

#### Points of Contact for Questions, Comments, and to Request Additional Information:

Ms. Linda Cole, NAVFAC Mid-Atlantic Remedial Program Manager and NWSY RAB Navy Co-Chair, (757) 322-4734

Mr. Jim Kemp, NWSY Public Affairs Officer, (757) 887-4939

Congratulations to Mr. Barry Moss on becoming the new NWSY RAB Community Co-Chair!

#### Naval Weapons Station Yorktown Restoration Advisory Board Meeting Minutes — 18 May 2005

Attachment 1: Public Notification of Meeting

#### STATE

#### Public Notice of RESTORATION ADVISORY BOARD MEETING For Naval Weapons Station Yorktown/Cheatham Annex

The Naval Facilities Engineering Command (NAVFAC), Mid-Atlantic, will hold a Restoration Advisory Board (RAB) Meeting at the following time and place:

Wednesday, May 18, 2005 from 6:30 p.m. to 8:30 p.m. Charles E. Brown Park Community Building, Old Williamsburg Road (Route 238) Lackey, Virginia (Near entrance to Gate No. 1)

#### The Public is Invited to Attend

The Naval Weapons Station Yorktown/Cheatham Annex RAB meets to discuss environmental issues and to inform the local community about base cleanup activities. This is your opportunity to participate in the process by providing direct input about base cleanup activities.

If you would like to receive additional information about the environmental cleanup program at Naval Wespons Station Yorktown/Cheatham Annex please contact:

Ms. Linda Colle, RAB Navy Co-Chair, at (757) 322-4734

NAVFAC Mid-Atlantic also holds RAB meetings for the following Naval facilities:

St. Juliens Creek Annex; Naval Amphibious Base, Little Creek; and Naval Station Norfolk



#### Naval Weapons Station Yorktown Restoration Advisory Board Meeting Minutes – 18 May 2005

Attachment 2: Attendance Sign-in Sheets

Lindo Cole	NAVFAC Mid-Atlantic	(757)322-4734	linda.cole@navy.mil
DON JOINER	BAKER ENV	사 활동을 하는 사람들은 경기를 하고 있다. 사람들은 경기를 하는 것이 되었다. 그는 것이 없는 것이 없다.	djoinere mtakercorp.com
MARLENE IVESTER	BAKER ENV		minester@makercop.com
BARAY 4055	HN RESIDENT	마네 그 사람과 사고가 하고, 어린 아이를 가는 사람들이 되는 것이 없는 사람들이 가는 것이 되었다. 그 아니는 그 얼마나 그 없다는 것이다.	BFMSS CCOX. NET
Wan Dy Browns	The Management Edge	(207)799 8687	
Tm Floor	The Management Chyl		Afterdal & trapplay on com
Grayson Franklin	US EPA	215 814 2333	franklin greyson osepn. g.
CHARLES WILSON	CNEMA ENVIRONMENTAL	757 887 7605	Wilsonch & pwchoruanaux mil
CHRIS KNUDSEN	NEGCHI		Christopher Knydser Enger
Jim Kem?	MWS YORKTOUU		KEM 75W & NUSY, NUMY, MIC
Hall Kemb	Glocister UA		The state of the s
Joe GURNNATO	BATLANTIC ORD COMMAN	287-4889	

		7	
Elizabeth C Roger	Ches Bay, York Chapter	757-14-9-3779	· Control of the Cont
JAY DEWING	CO CHAIR	757-259	
Cindy Barbeau	102 Jean Al. yokkowa, A	757-867-8261 (c) 218-0900	cintybarbeau @ cox .net
Sean Heaney	CNRMA Yorktown Fue Dayt	757 887 4086	heaveyss @ pwc.norva.muy.may
	•		
		and the second s	
		Basel of the control polytopic of the control	
	transporting the control of the following control program and the control of the		
		en e	
The second secon			

Attachment 3: Meeting Handout – Agenda and Presentations



## Naval Weapons Station Yorktown/Cheatham Annex

## Restoration Advisory Board Meeting 18 May 2005

Charles E. Brown Park Community
Building
Old Williamsburg Road

#### **AGENDA**

# ENVIRONMENTAL RESTORATION ADVISORY BOARD NAVAL WEAPONS STATION YORKTOWN AND CHEATHAM ANNEX CHARLES E. BROWN PARK COMMUNITY BUILDING


OLD WILLIAMSBURG ROAD (Route 238), LACKEY, VA

WEDNESDAY, 18 MAY 2005, 6:30 PM – 8:30 P.M.

WELCOME/INTRODUCTION	Mr. Jim Kemp	6:30-6:35
	Public Affairs Officer	
NAVY REMARKS	CAPT Philip G. Beierl	6:35-6:40
	Commanding Officer	
COMMUNITY REMARKS & FAREWELL	Mr. Jay Dewing	6:40-6:50
	Community Co-Chair	
ACKNOWLEDGEMENT OF SERVICE	CAPT Philip G. Beierl	6:50-6:55
FOR JAY DEWING	Commanding Officer	
SELECTION OF COMMUNITY CO-	Ms. Linda Cole	6:55-7:10
CHAIR	NAVFAC Mid-Atlantic	
BREAK		7:10-7:30
WORK PLANS FOR NWSY SITES 2 AND,	Mr. Don Joiner	7:30-7:50
WORK PLANS FOR NWSY SITES 2 AND, 8 AND SSA 14	Mr. Don Joiner Baker Environmental	7:30-7:50
	E .	7:30-7:50 7:50-8:10
8 AND SSA 14	Baker Environmental	
8 AND SSA 14 CAX SITE 7 EXPLOSIVE SAFETY	Baker Environmental Ms. Linda Cole	
8 AND SSA 14 CAX SITE 7 EXPLOSIVE SAFETY SUBMISSION	Baker Environmental Ms. Linda Cole NAVFAC Mid-Atlantic	7:50-8:10
8 AND SSA 14 CAX SITE 7 EXPLOSIVE SAFETY SUBMISSION NWSY SITE 4 ROD; DIFFERENCES	Baker Environmental Ms. Linda Cole NAVFAC Mid-Atlantic Mr. Don Joiner	7:50-8:10
8 AND SSA 14 CAX SITE 7 EXPLOSIVE SAFETY SUBMISSION NWSY SITE 4 ROD; DIFFERENCES FROM 2001 PRAP	Baker Environmental Ms. Linda Cole NAVFAC Mid-Atlantic Mr. Don Joiner Baker Environmental	7:50-8:10 8:10-8:25

#### **FUTURE RAB MEETINGS:**

Wednesday, 17 August 2005 Wednesday, 16 November 2005 Wednesday, 15 February 2006 Wednesday, 17 May 2006



### Naval Weapons Station Yorktown


Sites 2 and 8 and SSA 14 Removal Delineation Field Investigation

WPNSTA YORKTOWN RAB Meeting 18 May 2005




## Background

- Remedial Investigation (RI) for Site 2, Site 8, and Site Screening Area (SSA) 14 finalized June 2004
- Chemicals of Concern (COCs) identified at each site which may impact human health and/or the environment
- Planned remedy is removal based on small size of impacted areas at each location planned for Fall 2005
- Removal delineation planned for Summer 2005
  - Will further characterize the soil conditions at each site to support planned removal/remedial actions
  - Will delineate extent of identified human health and ecological COCs









- 5-acre disposal area located east of Turkey Road
- Operated from 1940s to 1981
- Wastes disposed (approximately 240 tons) include: batteries, tree stumps, construction rubble, hard waste material, electrical devices, and unidentified drums and/or tanks.
- Removal of hard waste material in Summer 1994




- 2004 RI identified the following COCs:
  - Polycyclic Aromatic Hydrocarbons (PAHs)
  - Polychlorinated Biphenyls (PCBs)
  - Metals: cadmium and mercury






#### Field Investigation Objectives

- Gather soil information (via trenching) to determine the extent of COCs within the former disposal area
- From each trench, collect at least one discrete, environmental soil sample and analyze for the COCs
- A total of 40 samples will be collected







## Site 8 - MEDED Explosives-Contaminated

## Wastewater Discharge Area





# Site 8 - NEDED Explosives-Contaminated Wastewater Discharge Area

- 300-foot long drainage way located along the eastern branch of Felgates Creek
- Area received wastewater from the Naval Explosives Development Engineering Department (NEDED) complex (Building 456) from 1940 to 1975
- Wastewater reportedly contained unspecified solvents, acids, and explosive compounds



# Site 8 - NEDED Explosives-Contaminated Wastewater Discharge Area


- 2004 RI identified the following COCs:
  - Explosives
  - PCBs
  - Metals: chromium, mercury, and zinc




# Site 8 - NEDED Explosives-Contaminated Wastewater Discharge Area

#### Field Investigation Objectives


- Gather soil information to determine the extent of COCs in the area immediately surrounding the Site 8 drainage ditch
- From each sample location, collect two discrete, environmental soil samples and analyze for the COCs
- A total of 16 samples will be collected (8 locations, two depths)







# SSA W - Building 537 Discharge to Felgates Creek





### SSA 14 - Building 537 Discharge to Felgates Creek

- 0.4 acre drainage way located along the eastern branch of Felgates Creek
- Upgradient of Site 8
- Area received explosive-contaminated wastewater from a pipe leading from Building 537



## SSA 14 - Building 537 Discharge to Felgates Creek

- 2004 RI identified the following COCs:
  - Explosives
  - Metals: mercury, selenium, and zinc






### SSA 14 - Building 537 Discharge to Felgates Creek

#### Field Investigation Objectives

- Gather soil information to determine the extent of COCs in the area surrounding the SSA 14 drainage tract
- From each sample location, collect two discrete, environmental soil samples and analyze for the COCs
- A total of 16 samples will be collected (8 locations, two depths)





## Reporting

- Data will be presented in Engineering Evaluations/Cost Analyses (EE/CAs) to support the removal effort
- Will define removal areas based on extent of contaminant concentrations exceeding cleanup goals
- Widespread contamination may warrant focused ecological evaluation prior to additional removal effort



## Questions or Comments?

For additional information contact:

Don Joiner

Baker Environmental, Inc.


770 Lynnhaven Parkway

Suite 240

Virginia Beach, VA 23452

757-631-5416


djoiner@mbakercorp.com



## Cheatham Annex Naval Weapons Station Yorktown

Site 7 Old DuPont Disposal Area Update

WPNSTA Yorktown RAB Meeting 18 May 2005





## Background

- Received waste from the City of Penniman and the DuPont shell loading plant
- Located near recreational cabins
- Debris from disposal area eroding onto beach and into York River
- Removed surface debris on beach May 2004
- Action Memo for Time-Critical Removal Action (TCRA) signed July 1, 2004 to mitigate further erosion




## Isabel Erosion





# Sloughing Hillside






# Beach Cleanup







## Typical Geotube Installation



Typical cross-section showing the relationship between the Mirafi<sup>®</sup> **Geotube**<sup>®</sup> and the Scour Apron. The intent of the apron is for the anchor tubes to bury themselves and protect the **Geotube**<sup>®</sup> from scour.




# Proposed Location of Geotube Bird's Eye View






#### Location of mortar shell found in June 2004





# Unfired, Unfuzed, 3-inch Projectile





### Military Munitions Definitions

- Military munitions means propellants, explosives, pyrotechnics, chemical and riot control agents, smokes, and incendiaries
- Does not include wholly inert items
- UXO means military munitions that have been primed, fuzed, or otherwise prepared for action and have been fired but remain unexploded
- Munitions and Explosives of Concern (MEC) include UXO, discarded military munitions, and munitions constituents



#### **Explosives Safety Submittal**

- Required before the start of munitions response activities
- Required before the start of any operations occurring at a site that involve:
  - The placement of explosives on a site
  - The intentional physical contact with munitions
  - The conduct of ground-disturbing or intrusive activities in areas known of suspected to contain MEC



#### ESS Waiver

- Former ranges used exclusively for training
- On-call construction support
- Activities employing anomaly avoidance with no unacceptable risks
- Construction response having a single military munitions response in area not known or suspected of having MEC



### Operational Risk/Hazard Assessment

Hazard Category	Mishap Probability A Likely	Mishap Probability B Probably in Time	Mishap Probability C  May Occur in Time	Mishap Probability D Unlikely to Occur
I-May Cause Death	1	1	2	3
II-Severe Injury	1	2	3	4
III-Minor Injury	2	3	4	5
<b>IV</b> -Minimal Threat	3	4	5	5



#### Path Forward


- Submitted preliminary draft of ESS to Naval Ordnance Safety & Security Activity
- Received 50 critical comments
- Incorporate comments and issue draft ESS to NOSSA for approval
- Revise work plan and begin geotube installation



### Questions or Comments?

For additional information contact:

Linda L. Cole
NAVFAC Mid-Atlantic
9742 Maryland Ave
Norfolk, VA 23511-3095
(757)322-4734
linda.cole@navy.mil



#### Naval Weapons Station Yorktown

Site 4 – Burning Pad Residue Landfill Record of Decision


WPNSTA Yorktown RAB Meeting 18 May 2005



## Background

- Approximately 10 acres
- Used as disposal area from 1940s until 1975
- Materials disposed included
  - Carbon-zinc batteries
  - Burning pad residues
  - Fly ash from coal-fired boilers
  - Mine casings
  - Electrical equipment
  - General construction debris





Magazine Group No ng Felgates Creek Site 4 Site 21 Site 22/



# History of Investigations

- Round One RI completed in 1993
- Surface debris removal action in 1994
- Round Two RI completed in 2001
- Feasibility Study completed in 2001
- Proposed Plan completed in 2001
- Public Meeting held on February 21, 2001



# Proposed Plan Public Meeting

- Preferred alternative in the Proposed Plan included excavation with off-site disposal
  - Prevents potential human and ecological exposure to PAHs, 2,4,6-TNT, and metals
  - Soil removed to meet industrial cleanup levels




#### 2005 NTCRA

- A non-time-critical removal action (NTCRA) was completed in 2005
- The NTCRA initially included removal of contaminated soil exceeding industrial cleanup goals
- During the NTCRA, cleanup goals were revised to meet residential and ecological risk criteria
- Eliminates need for land use controls











#### No Further Action ROD

- ROD addresses soil only; groundwater will be addressed as part of a separate operable unit
- No Further Action because the 2005 NTCRA remediated unacceptable risks to human and ecological receptors
- ROD includes Documentation of Significant Changes since remedy differs from that presented to the public on 2/21/01



### Goal

ROD signature by September 2005



#### Questions or Comments?

For additional information contact:

Don Joiner

Baker Environmental, Inc.

770 Lynnhaven Parkway

Suite 240

Virginia Beach, VA 23452

757-631-5416

djoiner@mbakercorp.com